

From: [Kady, Thomas](#)
To: jonathan.d.mcburney@lmco.com
Cc: [Coltrain, Katrina](#)
Subject: Wilcox report
Date: Sunday, April 24, 2016 2:18:22 PM

Jon-

While reviewing the report with Katrina, she mentioned it appears the L I F missed the LNAPL near the well behind the church on the Lorraine property. In reviewing the figure, the reason is because many of the boring locations behind the church were inaccessible due to the rig sinking in the mud. Please modify the figure by marking each boring location we could not access with an appropriate symbol. Also provide a footnote explaining the absence of contaminant contour lines in areas where borings were not performed does not necessarily indicate the absence of contamination.

Thanks

Tom

Sent from my iPhone



9750835